GENTILE | HOLLOWAY | O'MAHONEY & Associates, Inc.

George G. Gentile FASLA M. Troy Holloway ASLA Emily M. O'Mahoney FASLA

April 18, 2022

Mary Savage-Dunham, AICP Department of Development Services 600 W. Blue Heron Boulevard Riviera Beach, FL 33404

Re: Viking Sales and Service – Valhalla Boat Sales – PA 21-04

Dear Mary,

Pursuant to comments received from staff on December 21, 2021 please accept this letter as a written response. Also included, is the revised plat documents which address the comments where applicable.

Engenuity Group - Gary Rayman

Sheet One.

1. The sub-title needs to be amended to reflect that the westerly 15 feet of lots 10-14 Block 8 a are not included in this replat. Also, in the first paragraph of the Dedications and Reservations.

Response: Sub-Title amended as requested.

- 2. In the first paragraph of the Dedication and Reservations, Inlet Grove is misspelled. **Response: Misspelling was corrected as noted**
- 3. In the paragraph before the last of the Dedication and Reservations, "the purposes consistent" omit "the" and correct the spelling of "purposes".

Response: Misspelling was corrected as noted

4. In the Reviewing Surveyor's Certificate, change Nick Miller to Gary M. Rayman PLS. 2633; Project Manager.

Response: Reviewing surveyors name revised as requested.

5. In the City of Riviera Beach Approval, the name of the attestor, Terrence N. Bailey. E., is misspelled.

Response: Misspelling was corrected as noted

6. In item 1. of the Surveyors & Mapper's Notes, the wrong line is struck out and Plat Book 130; Pages I & 2 does not apply to this plat.

1. Show ties from the plat boundaries to the centerline of the adjoining streets. (Tarpon Ave., Inlet Ave., Curtiss St., U.S. Highway No. 1 and Oak St.), **Response: Added ties to centerline per request.**

2. Show a tie between Block 7 and Block 8 across Tarpon Ave. (also on Sheet 3). Response: Removed "Regions Tequesta" from east line.

Sheet Three.

- 1. The note pointing to the West line of Lot 5, Block 8, is incorrectly labelled as Block 16. Response: Previous platting of blocks 7 & 8 revised to now platting blocks 8 & 9
- 2. The note pointing to the East line of Lot 18, Block 8, is incorrectly labelled as Block 16. Response: Previous platting of blocks 7 & 8 revised to now platting blocks 8 & 9

General.

It would be helpful to show the areas of the two tracts being created by this plat.

Response: Limits of the tracts are noted as requested.

Engineering - Terrance Bailey


Plat PA-21-04 Comments:

6. Corner clips are required along Broadway (25') and Avenue C (15') at 15th and 16th. Please dedicate these triangles as right of way on the plat or by separate instrument.


Response: Corner clips added to the plat as requested.

- 7. Please make the revisions to the plat cover page as shown below:
 - a. Add names and PE/SI numbers to the signature circles

Response: Information added to signature circles as requested.



b. Please add the language on the resolution authorizing execution of the plat to the top right corner of the cover page.



Sincerely, 2GHO, Inc.

George G. Gentile, PLA, FASLA

GENTILE | HOLLOWAY | O'MAHONEY & Associates, Inc.

George G. Gentile FASLA M. Troy Holloway ASLA Emily M. O'Mahoney FASLA

April 18, 2022

Mary Savage-Dunham, AICP Department of Development Services 600 W. Blue Heron Boulevard Riviera Beach, FL 33404

Re: Viking Sales and Service – Valhalla Boat Sales – PA 21-04

Dear Mary,

Pursuant to comments received from staff on December 21, 2021 please accept this letter as a written response. Also included, is the revised plat documents which address the comments where applicable.

Engenuity Group - Gary Rayman

Sheet One.

1. The sub-title needs to be amended to reflect that the westerly 15 feet of lots 10-14 Block 8 a are not included in this replat. Also, in the first paragraph of the Dedications and Reservations.

Response: Sub-Title amended as requested.

- 2. In the first paragraph of the Dedication and Reservations, Inlet Grove is misspelled. **Response: Misspelling was corrected as noted**
- 3. In the paragraph before the last of the Dedication and Reservations, "the purposes consistent" omit "the" and correct the spelling of "purposes".

Response: Misspelling was corrected as noted

4. In the Reviewing Surveyor's Certificate, change Nick Miller to Gary M. Rayman PLS. 2633; Project Manager.

Response: Reviewing surveyors name revised as requested.

5. In the City of Riviera Beach Approval, the name of the attestor, Terrence N. Bailey. E., is misspelled.

Response: Misspelling was corrected as noted

6. In item 1. of the Surveyors & Mapper's Notes, the wrong line is struck out and Plat Book 130; Pages I & 2 does not apply to this plat.

1. Show ties from the plat boundaries to the centerline of the adjoining streets. (Tarpon Ave., Inlet Ave., Curtiss St., U.S. Highway No. 1 and Oak St.), **Response: Added ties to centerline per request.**

2. Show a tie between Block 7 and Block 8 across Tarpon Ave. (also on Sheet 3). Response: Removed "Regions Tequesta" from east line.

Sheet Three.

- 1. The note pointing to the West line of Lot 5, Block 8, is incorrectly labelled as Block 16. Response: Previous platting of blocks 7 & 8 revised to now platting blocks 8 & 9
- 2. The note pointing to the East line of Lot 18, Block 8, is incorrectly labelled as Block 16. Response: Previous platting of blocks 7 & 8 revised to now platting blocks 8 & 9

General.

It would be helpful to show the areas of the two tracts being created by this plat.

Response: Limits of the tracts are noted as requested.

Engineering - Terrance Bailey


Plat PA-21-04 Comments:

6. Corner clips are required along Broadway (25') and Avenue C (15') at 15th and 16th. Please dedicate these triangles as right of way on the plat or by separate instrument.


Response: Corner clips added to the plat as requested.

- 7. Please make the revisions to the plat cover page as shown below:
 - a. Add names and PE/SI numbers to the signature circles

Response: Information added to signature circles as requested.



b. Please add the language on the resolution authorizing execution of the plat to the top right corner of the cover page.



Sincerely, 2GHO, Inc.

George G. Gentile, PLA, FASLA

GENTILE | HOLLOWAY | O'MAHONEY & Associates, Inc.

George G. Gentile FASLA M. Troy Holloway ASLA Emily M. O'Mahoney FASLA

April 18, 2022

Mary Savage-Dunham, AICP Department of Development Services 600 W. Blue Heron Boulevard Riviera Beach, FL 33404

Re: Viking Sales and Service – Valhalla Boat Sales – PA 21-04

Dear Mary,

Pursuant to comments received from staff on December 21, 2021 please accept this letter as a written response. Also included, is the revised plat documents which address the comments where applicable.

Engenuity Group - Gary Rayman

Sheet One.

1. The sub-title needs to be amended to reflect that the westerly 15 feet of lots 10-14 Block 8 a are not included in this replat. Also, in the first paragraph of the Dedications and Reservations.

Response: Sub-Title amended as requested.

- 2. In the first paragraph of the Dedication and Reservations, Inlet Grove is misspelled. **Response: Misspelling was corrected as noted**
- 3. In the paragraph before the last of the Dedication and Reservations, "the purposes consistent" omit "the" and correct the spelling of "purposes".

Response: Misspelling was corrected as noted

4. In the Reviewing Surveyor's Certificate, change Nick Miller to Gary M. Rayman PLS. 2633; Project Manager.

Response: Reviewing surveyors name revised as requested.

5. In the City of Riviera Beach Approval, the name of the attestor, Terrence N. Bailey. E., is misspelled.

Response: Misspelling was corrected as noted

6. In item 1. of the Surveyors & Mapper's Notes, the wrong line is struck out and Plat Book 130; Pages I & 2 does not apply to this plat.

1. Show ties from the plat boundaries to the centerline of the adjoining streets. (Tarpon Ave., Inlet Ave., Curtiss St., U.S. Highway No. 1 and Oak St.), **Response: Added ties to centerline per request.**

2. Show a tie between Block 7 and Block 8 across Tarpon Ave. (also on Sheet 3). Response: Removed "Regions Tequesta" from east line.

Sheet Three.

- 1. The note pointing to the West line of Lot 5, Block 8, is incorrectly labelled as Block 16. Response: Previous platting of blocks 7 & 8 revised to now platting blocks 8 & 9
- 2. The note pointing to the East line of Lot 18, Block 8, is incorrectly labelled as Block 16. Response: Previous platting of blocks 7 & 8 revised to now platting blocks 8 & 9

General.

It would be helpful to show the areas of the two tracts being created by this plat.

Response: Limits of the tracts are noted as requested.

Engineering - Terrance Bailey


Plat PA-21-04 Comments:

6. Corner clips are required along Broadway (25') and Avenue C (15') at 15th and 16th. Please dedicate these triangles as right of way on the plat or by separate instrument.


Response: Corner clips added to the plat as requested.

- 7. Please make the revisions to the plat cover page as shown below:
 - a. Add names and PE/SI numbers to the signature circles

Response: Information added to signature circles as requested.



b. Please add the language on the resolution authorizing execution of the plat to the top right corner of the cover page.



Sincerely, 2GHO, Inc.

George G. Gentile, PLA, FASLA

GENTILE | HOLLOWAY | O'MAHONEY & Associates, Inc.

George G. Gentile FASLA M. Troy Holloway ASLA Emily M. O'Mahoney FASLA

April 18, 2022

Mary Savage-Dunham, AICP Department of Development Services 600 W. Blue Heron Boulevard Riviera Beach, FL 33404

Re: Viking Sales and Service – Valhalla Boat Sales – PA 21-04

Dear Mary,

Pursuant to comments received from staff on December 21, 2021 please accept this letter as a written response. Also included, is the revised plat documents which address the comments where applicable.

Engenuity Group - Gary Rayman

Sheet One.

1. The sub-title needs to be amended to reflect that the westerly 15 feet of lots 10-14 Block 8 a are not included in this replat. Also, in the first paragraph of the Dedications and Reservations.

Response: Sub-Title amended as requested.

- 2. In the first paragraph of the Dedication and Reservations, Inlet Grove is misspelled. **Response: Misspelling was corrected as noted**
- 3. In the paragraph before the last of the Dedication and Reservations, "the purposes consistent" omit "the" and correct the spelling of "purposes".

Response: Misspelling was corrected as noted

4. In the Reviewing Surveyor's Certificate, change Nick Miller to Gary M. Rayman PLS. 2633; Project Manager.

Response: Reviewing surveyors name revised as requested.

5. In the City of Riviera Beach Approval, the name of the attestor, Terrence N. Bailey. E., is misspelled.

Response: Misspelling was corrected as noted

6. In item 1. of the Surveyors & Mapper's Notes, the wrong line is struck out and Plat Book 130; Pages I & 2 does not apply to this plat.

1. Show ties from the plat boundaries to the centerline of the adjoining streets. (Tarpon Ave., Inlet Ave., Curtiss St., U.S. Highway No. 1 and Oak St.), **Response: Added ties to centerline per request.**

2. Show a tie between Block 7 and Block 8 across Tarpon Ave. (also on Sheet 3). Response: Removed "Regions Tequesta" from east line.

Sheet Three.

- 1. The note pointing to the West line of Lot 5, Block 8, is incorrectly labelled as Block 16. Response: Previous platting of blocks 7 & 8 revised to now platting blocks 8 & 9
- 2. The note pointing to the East line of Lot 18, Block 8, is incorrectly labelled as Block 16. Response: Previous platting of blocks 7 & 8 revised to now platting blocks 8 & 9

General.

It would be helpful to show the areas of the two tracts being created by this plat.

Response: Limits of the tracts are noted as requested.

Engineering - Terrance Bailey


Plat PA-21-04 Comments:

6. Corner clips are required along Broadway (25') and Avenue C (15') at 15th and 16th. Please dedicate these triangles as right of way on the plat or by separate instrument.


Response: Corner clips added to the plat as requested.

- 7. Please make the revisions to the plat cover page as shown below:
 - a. Add names and PE/SI numbers to the signature circles

Response: Information added to signature circles as requested.



b. Please add the language on the resolution authorizing execution of the plat to the top right corner of the cover page.



Sincerely, 2GHO, Inc.

George G. Gentile, PLA, FASLA

GENTILE HOLLOWAY O'MAHONEY & Associates, Inc.

George G. Gentile FASLA M. Troy Holloway ASLA Emily M. O'Mahoney FASLA

April 18, 2022

Mary Savage-Dunham, AICP Department of Development Services 600 W. Blue Heron Boulevard Riviera Beach, FL 33404

Re: Viking Sales and Service – Valhalla Boat Sales – PA 21-04

Dear Mary,

Pursuant to comments received from staff on December 21, 2021 please accept this letter as a written response. Also included, is the revised plat documents which address the comments where applicable.

Engenuity Group – Gary Rayman

Sheet One.

1. The sub-title needs to be amended to reflect that the westerly 15 feet of lots 10-14 Block 8 a are not included in this replat. Also, in the first paragraph of the Dedications and Reservations.

Response: Sub-Title amended as requested.

- 2. In the first paragraph of the Dedication and Reservations, Inlet Grove is misspelled. **Response: Misspelling was corrected as noted**
- 3. In the paragraph before the last of the Dedication and Reservations, "the purposes consistent" omit "the" and correct the spelling of "purposes".

Response: Misspelling was corrected as noted

4. In the Reviewing Surveyor's Certificate, change Nick Miller to Gary M. Rayman PLS. 2633; Project Manager.

Response: Reviewing surveyors name revised as requested.

5. In the City of Riviera Beach Approval, the name of the attestor, Terrence N. Bailey. E., is misspelled.

Response: Misspelling was corrected as noted

6. In item 1. of the Surveyors & Mapper's Notes, the wrong line is struck out and Plat Book 130; Pages I & 2 does not apply to this plat.

1. Show ties from the plat boundaries to the centerline of the adjoining streets. (Tarpon Ave., Inlet Ave., Curtiss St., U.S. Highway No. 1 and Oak St.), **Response: Added ties to centerline per request.**

2. Show a tie between Block 7 and Block 8 across Tarpon Ave. (also on Sheet 3). Response: Removed "Regions Tequesta" from east line.

Sheet Three.

- 1. The note pointing to the West line of Lot 5, Block 8, is incorrectly labelled as Block 16. Response: Previous platting of blocks 7 & 8 revised to now platting blocks 8 & 9
- 2. The note pointing to the East line of Lot 18, Block 8, is incorrectly labelled as Block 16. Response: Previous platting of blocks 7 & 8 revised to now platting blocks 8 & 9

General.

It would be helpful to show the areas of the two tracts being created by this plat.

Response: Limits of the tracts are noted as requested.

Engineering - Terrance Bailey


Plat PA-21-04 Comments:

6. Corner clips are required along Broadway (25') and Avenue C (15') at 15th and 16th. Please dedicate these triangles as right of way on the plat or by separate instrument.


Response: Corner clips added to the plat as requested.

- 7. Please make the revisions to the plat cover page as shown below:
 - a. Add names and PE/SI numbers to the signature circles

Response: Information added to signature circles as requested.



b. Please add the language on the resolution authorizing execution of the plat to the top right corner of the cover page.



Sincerely, 2GHO, Inc.

George G. Gentile, PLA, FASLA

GENTILE HOLLOWAY O'MAHONEY & Associates, Inc.

George G. Gentile FASLA M. Troy Holloway ASLA Emily M. O'Mahoney FASLA

April 18, 2022

Mary Savage-Dunham, AICP Department of Development Services 600 W. Blue Heron Boulevard Riviera Beach, FL 33404

Re: Viking Sales and Service – Valhalla Boat Sales – PA 21-04

Dear Mary,

Pursuant to comments received from staff on December 21, 2021 please accept this letter as a written response. Also included, is the revised plat documents which address the comments where applicable.

Engenuity Group – Gary Rayman

Sheet One.

1. The sub-title needs to be amended to reflect that the westerly 15 feet of lots 10-14 Block 8 a are not included in this replat. Also, in the first paragraph of the Dedications and Reservations.

Response: Sub-Title amended as requested.

- 2. In the first paragraph of the Dedication and Reservations, Inlet Grove is misspelled. **Response: Misspelling was corrected as noted**
- 3. In the paragraph before the last of the Dedication and Reservations, "the purposes consistent" omit "the" and correct the spelling of "purposes".

Response: Misspelling was corrected as noted

4. In the Reviewing Surveyor's Certificate, change Nick Miller to Gary M. Rayman PLS. 2633; Project Manager.

Response: Reviewing surveyors name revised as requested.

5. In the City of Riviera Beach Approval, the name of the attestor, Terrence N. Bailey. E., is misspelled.

Response: Misspelling was corrected as noted

6. In item 1. of the Surveyors & Mapper's Notes, the wrong line is struck out and Plat Book 130; Pages I & 2 does not apply to this plat.

1. Show ties from the plat boundaries to the centerline of the adjoining streets. (Tarpon Ave., Inlet Ave., Curtiss St., U.S. Highway No. 1 and Oak St.), **Response: Added ties to centerline per request.**

2. Show a tie between Block 7 and Block 8 across Tarpon Ave. (also on Sheet 3). Response: Removed "Regions Tequesta" from east line.

Sheet Three.

- 1. The note pointing to the West line of Lot 5, Block 8, is incorrectly labelled as Block 16. Response: Previous platting of blocks 7 & 8 revised to now platting blocks 8 & 9
- 2. The note pointing to the East line of Lot 18, Block 8, is incorrectly labelled as Block 16. Response: Previous platting of blocks 7 & 8 revised to now platting blocks 8 & 9

General.

It would be helpful to show the areas of the two tracts being created by this plat.

Response: Limits of the tracts are noted as requested.

Engineering - Terrance Bailey


Plat PA-21-04 Comments:

6. Corner clips are required along Broadway (25') and Avenue C (15') at 15th and 16th. Please dedicate these triangles as right of way on the plat or by separate instrument.


Response: Corner clips added to the plat as requested.

- 7. Please make the revisions to the plat cover page as shown below:
 - a. Add names and PE/SI numbers to the signature circles

Response: Information added to signature circles as requested.



b. Please add the language on the resolution authorizing execution of the plat to the top right corner of the cover page.



Sincerely, 2GHO, Inc.

George G. Gentile, PLA, FASLA

GENTILE HOLLOWAY O'MAHONEY & Associates, Inc.

George G. Gentile FASLA M. Troy Holloway ASLA Emily M. O'Mahoney FASLA

April 18, 2022

Mary Savage-Dunham, AICP Department of Development Services 600 W. Blue Heron Boulevard Riviera Beach, FL 33404

Re: Viking Sales and Service – Valhalla Boat Sales – PA 21-04

Dear Mary,

Pursuant to comments received from staff on December 21, 2021 please accept this letter as a written response. Also included, is the revised plat documents which address the comments where applicable.

Engenuity Group – Gary Rayman

Sheet One.

1. The sub-title needs to be amended to reflect that the westerly 15 feet of lots 10-14 Block 8 a are not included in this replat. Also, in the first paragraph of the Dedications and Reservations.

Response: Sub-Title amended as requested.

- 2. In the first paragraph of the Dedication and Reservations, Inlet Grove is misspelled. **Response: Misspelling was corrected as noted**
- 3. In the paragraph before the last of the Dedication and Reservations, "the purposes consistent" omit "the" and correct the spelling of "purposes".

Response: Misspelling was corrected as noted

4. In the Reviewing Surveyor's Certificate, change Nick Miller to Gary M. Rayman PLS. 2633; Project Manager.

Response: Reviewing surveyors name revised as requested.

5. In the City of Riviera Beach Approval, the name of the attestor, Terrence N. Bailey. E., is misspelled.

Response: Misspelling was corrected as noted

6. In item 1. of the Surveyors & Mapper's Notes, the wrong line is struck out and Plat Book 130; Pages I & 2 does not apply to this plat.

1. Show ties from the plat boundaries to the centerline of the adjoining streets. (Tarpon Ave., Inlet Ave., Curtiss St., U.S. Highway No. 1 and Oak St.), **Response: Added ties to centerline per request.**

2. Show a tie between Block 7 and Block 8 across Tarpon Ave. (also on Sheet 3). Response: Removed "Regions Tequesta" from east line.

Sheet Three.

- 1. The note pointing to the West line of Lot 5, Block 8, is incorrectly labelled as Block 16. Response: Previous platting of blocks 7 & 8 revised to now platting blocks 8 & 9
- 2. The note pointing to the East line of Lot 18, Block 8, is incorrectly labelled as Block 16. Response: Previous platting of blocks 7 & 8 revised to now platting blocks 8 & 9

General.

It would be helpful to show the areas of the two tracts being created by this plat.

Response: Limits of the tracts are noted as requested.

Engineering - Terrance Bailey


Plat PA-21-04 Comments:

6. Corner clips are required along Broadway (25') and Avenue C (15') at 15th and 16th. Please dedicate these triangles as right of way on the plat or by separate instrument.


Response: Corner clips added to the plat as requested.

- 7. Please make the revisions to the plat cover page as shown below:
 - a. Add names and PE/SI numbers to the signature circles

Response: Information added to signature circles as requested.



b. Please add the language on the resolution authorizing execution of the plat to the top right corner of the cover page.



Sincerely, 2GHO, Inc.

George G. Gentile, PLA, FASLA